



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138

## PRODUCT/PROCESS CHANGE NOTICE (PCN)

PCN #: **A1208-01R1**      DATE: **December 21, 2012**  
 Product Affected:    SOIC, TSSOP, VFQFPN, SSOP,  
                                     TQFP, QSOP  
                                     (Refer to updated affected part list in Attachment 2)  
 Date Effective:        **March 21, 2013**

MEANS OF DISTINGUISHING CHANGED DEVICES:

Product Mark  
 Back Mark      Lot# will have a "Y" suffix  
 Date Code  
 Other

Contact:            Bimla Paul  
 Title:                Product Quality Assurance  
 Phone #:            (408) 574-6419  
 Fax #:               (408) 284-8362  
 E-mail:              [Bimla.Paul@idt.com](mailto:Bimla.Paul@idt.com)

Attachment:          Yes                                     No  
 Samples:      Samples available upon request

### DESCRIPTION AND PURPOSE OF CHANGE:

- Die Technology
- Wafer Fabrication Process
- Assembly Process
- Equipment
- Material
- Testing
- Manufacturing Site
- Data Sheet
- Other

**Revision 1:** This revised notification is to remove selected devices from the affected part list and to add devices to the affected part list. PCN effective date will be pushed out to March 21, 2013.

Attachment 3 shows part numbers removed from the revised PCN.  
 Attachment 4 shows part numbers added into the revised PCN.

**Original Notice:**

This notification is to advise our customers that IDT plans to change from Gold bond wire to Copper bond wire for the selective products. This change is applicable to all the existing qualified assembly sub-contractors of the affected part numbers.

There is no change in the moisture sensitivity performance.

Please refer to the following attachments for additional information.  
 Attachment 1 outlines the qualification results.  
 Attachment 2 shows the affected part numbers.

### RELIABILITY/QUALIFICATION SUMMARY:

There is no expected change to the product quality or reliability performance.

### CUSTOMER ACKNOWLEDGMENT OF RECEIPT:

IDT records indicate that you require written notification of this change. Please use the acknowledgement below or E-Mail to grant approval or request additional information. If IDT does not receive acknowledgement within 90 days of this notice it will be assumed that this change is acceptable.  
 IDT reserves the right to ship either version manufactured after the process change effective date until the inventory on the earlier version has been depleted.

|                  |   |
|------------------|---|
| Customer: _____  | <input type="checkbox"/> <i>Approval for shipments prior to effective date.</i> |
| Name/Date: _____ | E-Mail Address: _____   |
| Title: _____     | Phone# /Fax# : _____  |

### CUSTOMER COMMENTS:

### IDT ACKNOWLEDGMENT OF RECEIPT:

RECD. BY: \_\_\_\_\_      DATE: \_\_\_\_\_



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138

## PRODUCT/PROCESS CHANGE NOTICE (PCN)

### ATTACHMENT 1 - PCN # : A1208-01R1

**PCN Type:** Assembly Material Change - Gold Wire to Copper Wire

**Data Sheet Change:** None

**Details Of Change:**

This notification is to advise our customers that IDT plans to change from Gold bond wire to Copper bond wire for the selective products. This change is applicable to all the existing qualified assembly sub-contractors of the affected part numbers.

There is no change to the moisture performance of these packages.

Customers may expect to receive shipments with Copper wire process no sooner than 90 days from the date of this notification, December 21, 2012. Product assembled with Gold wire and Copper wire will be shipped during the transition period or until the Gold wire inventory has been depleted. However please note that product assembled with Gold wire and Copper wire will not be mixed in one tray stack, or tape and reel.

We request you to acknowledge receipt of this notification within 30 days of the date of this PCN notification. If you require samples to conduct an evaluation, please make your sample request within 30 days as samples are not built ahead of the change for all device options. You may contact your local sales representative to acknowledge this PCN and request samples.

**Assembly Material :** There is no change in the mold compound and die attach materials. The material sets used in assembly is in compliance with RoHS 5 (standard products) and RoHS 6 (green products) requirement. There is no change in the moisture sensitivity performance.

**Sample Availability :** Samples are not built ahead of the change for all device types and may not be available for all affected device types.  
Please contact your local IDT sales representative for your sample request and availability.



**PRODUCT/PROCESS CHANGE NOTICE (PCN)**

**ATTACHMENT 1 - PCN # : A1208-01R1**

**Qualification Test Result :**

Qual Vehicle: i) 18.40mm x 7.50mm SSOP-56

| Test Description  | Test Method | Test Results (SS / Rej) |      |      |
|---|-------------|-------------------------|------|------|
|   |             | Lot1                    | Lot2 | Lot3 |
| * High Accelerated Stress Test<br>(Biased, 130 °C/85% RH, 96 Hrs) | JESD22-A110 | 45/0                    | 45/0 | 45/0 |
| * Temperature Cycle / Condition B<br>(-55 °C to +125 °C, 700 Cyc) | JESD22-A104 | 45/0                    | 45/0 | 45/0 |
| High Temp. Storage Test<br>(150 °C, 1000 Hrs)                     | JESD22-A103 | 77/0                    | 77/0 | 77/0 |
| Bond Shear  | JESD22-B116 | 5/0                     | 5/0  | 5/0  |

Note:

\* Test requires moisture pre-conditioning sequence per JESD22-A113C and will use the existing moisture sensitivity level that has been qualified for this material set.

Qual Vehicle: ii) 17.00mm x 6.10mm TSSOP-64

| Test Description  | Test Method | Test Results (SS / Rej) |                   |      |
|---|-------------|-------------------------|-------------------|------|
|   |             | Lot1                    | Lot2              | Lot3 |
| * High Accelerated Stress Test<br>(Biased, 130 °C/85% RH, 96 Hrs) | JESD22-A110 | 45/0                    | 45/0              | 45/0 |
| * Temperature Cycle / Condition B<br>(-55 °C to +125 °C, 700 Cyc) | JESD22-A104 | 45/0                    | <sup>2</sup> 44/0 | 45/0 |
| High Temp. Storage Test<br>(150 °C, 1000 Hrs)                     | JESD22-A103 | <sup>2</sup> 76/0       | <sup>2</sup> 76/0 | 77/0 |
| Bond Shear  | JESD22-B116 | 5/0                     | 5/0               | 5/0  |

Note:

\* Test requires moisture pre-conditioning sequence per JESD22-A113C and will use the existing moisture sensitivity level that has been qualified for this material set.

<sup>2</sup> mechanical reject



## PRODUCT/PROCESS CHANGE NOTICE (PCN)

### ATTACHMENT 1 - PCN # : A1208-01R1

**Qualification Test Result :**

Qual Vehicle: iii) 5.00mm x 5.00mm VFQFPN-32

| Test Description  | Test Method | Test Results (SS / Rej) |      |      |
|---|-------------|-------------------------|------|------|
|   |             | Lot1                    | Lot2 | Lot3 |
| * High Accelerated Stress Test<br>(Biased, 130 °C/85% RH, 96 Hrs) | JESD22-A110 | 25/0                    | 25/0 | 25/0 |
| * Temperature Cycle / Condition B<br>(-55 °C to +125 °C, 700 Cyc) | JESD22-A104 | 25/0                    | 25/0 | 25/0 |
| High Temp. Storage Test<br>(150 °C, 1000 Hrs)                     | JESD22-A103 | 25/0                    | 25/0 | 25/0 |
| Bond Shear  | JESD22-B116 | 5/0                     | 5/0  | 5/0  |

Note:

\* Test requires moisture pre-conditioning sequence per JESD22-A113C and will use the existing moisture sensitivity level that has been qualified for this material set.

Qual Vehicle: iv) 7.00mm x 7.00mm TQFP-32

| Test Description  | Test Method | Test Results (SS / Rej) |      |                   |
|---|-------------|-------------------------|------|-------------------|
|   |             | Lot1                    | Lot2 | Lot3              |
| * High Accelerated Stress Test<br>(Biased, 130 °C/85% RH, 96 Hrs) | JESD22-A110 | 25/0                    | 25/0 | 25/0              |
| * Temperature Cycle / Condition B<br>(-55 °C to +125 °C, 700 Cyc) | JESD22-A104 | 25/0                    | 25/0 | 25/0              |
| High Temp. Storage Test<br>(150 °C, 1000 Hrs)                     | JESD22-A103 | 25/0                    | 25/0 | <sup>2</sup> 24/0 |
| Bond Shear  | JESD22-B116 | 5/0                     | 5/0  | 5/0               |

Note:

\* Test requires moisture pre-conditioning sequence per JESD22-A113C and will use the existing moisture sensitivity level that has been qualified for this material set.

<sup>2</sup> mechanical reject

### 2. Product Electrical Characterization

Product electrical characterization has been successfully completed on representative product families and copper wire performance was comparable to gold wire performance.



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138

## PRODUCT/PROCESS CHANGE NOTICE (PCN)

### ATTACHMENT 2 - PCN #: A1208-01R1

#### Updated Affected Part Numbers

| IDT Part Number | IDT Part Number | IDT Part Number | IDT Part Number |
|-----------------|-----------------|-----------------|-----------------|
| 1337DCGI        | 2304NZG-1LF     | 2308-1DCGI      | 2308B-2DCG      |
| 1337DCGI8       | 2304NZG-1LFT    | 2308-1DCGI8     | 2308B-2DCG8     |
| 1337GDCGI       | 2304NZGI-1LF    | 2308-1HDCG      | 2308B-2DCGI     |
| 1337GDCGI8      | 2304NZGI-1LFT   | 2308-1HDCG8     | 2308B-2DCGI8    |
| 1337GDCGK       | 2305-1DCG       | 2308-1HDCGI     | 2308B-5HPGG     |
| 1337GDCGK8      | 2305-1DCG8      | 2308-1HDCGI8    | 2308B-5HPGG8    |
| 1338-18DCGI     | 2305-1DCGI      | 2308-2DCG       | 2309-1DCG       |
| 1338-18DCGI8    | 2305-1DCGI8     | 2308-2DCG8      | 2309-1DCG8      |
| 1338-31DCGI     | 2305-1HDCG      | 2308-2DCGI      | 2309-1DCGI      |
| 1338-31DCGI8    | 2305-1HDCG8     | 2308-2DCGI8     | 2309-1DCGI8     |
| 1338-31DVGI     | 2305-1HDCGI     | 2308-4DCG       | 2309-1HDCG      |
| 1338-31DVGI8    | 2305-1HDCGI8    | 2308-4DCG8      | 2309-1HDCG8     |
| 1339-2DCGI      | 2305A-1DCG      | 2308-4DCGI      | 2309-1HDCGI     |
| 1339-2DCGI8     | 2305A-1DCG8     | 2308-4DCGI8     | 2309-1HDCGI8    |
| 1339-31DVGI     | 2305A-1DCGI     | 2308-5HDCG      | 2309A-1DCG      |
| 1339-31DVGI8    | 2305A-1DCGI8    | 2308-5HDCG8     | 2309A-1DCG8     |
| 1493G-20LF      | 2305A-1HDCG     | 2308-5HDCGI     | 2309A-1DCGI     |
| 1493G-20LFT     | 2305A-1HDCG8    | 2308-5HDCGI8    | 2309A-1DCGI8    |
| 1523MLF         | 2305A-1HDCGI    | 2308A-1DCG      | 2309M-1         |
| 1523MLFT        | 2305A-1HDCGI8   | 2308A-1DCG8     | 2309M-1HLF      |
| 1526GILF        | 2305B-1DCG      | 2308A-1DCGI     | 2309M-1HLFT     |
| 1526GILFT       | 2305B-1DCG8     | 2308A-1DCGI8    | 2309M-1T        |
| 1526GLF         | 2305B-1DCGI     | 2308A-1HDCG     | 2309MI-1        |
| 1526GLFT        | 2305B-1DCGI8    | 2308A-1HDCG8    | 2309MI-1HLF     |
| 1574BMLF        | 2305B-1HDCG     | 2308A-1HDCGI    | 2309MI-1HLFT    |
| 1574BMLFT       | 2305B-1HDCG8    | 2308A-1HDCGI8   | 2309MI-1T       |
| 180M-01LF       | 2305B-1HDCGI    | 2308A-2DCG      | 2309NZ-1HDCG    |
| 180M-01LFT      | 2305B-1HDCGI8   | 2308A-2DCG8     | 2309NZ-1HDCG8   |
| 180M-51LF       | 2305M-1LF       | 2308A-2DCGI     | 2309NZ-1HDCGI   |
| 180M-51LFT      | 2305M-1LFT      | 2308A-2DCGI8    | 2309NZ-1HDCGI8  |
| 180M-53LF       | 2305MI-1LF      | 2308A-4DCG      | 23S05-1DCG      |
| 180M-53LFT      | 2305MI-1LFT     | 2308A-4DCG8     | 23S05-1DCG8     |
| 180MI-01LF      | 2305NZ-1HDCG    | 2308A-4DCGI     | 23S05-1DCGI     |
| 180MI-01LFT     | 2305NZ-1HDCG8   | 2308A-4DCGI8    | 23S05-1DCGI8    |
| 181M-02LF       | 2305NZ-1HDCGI   | 2308B-1DCG      | 23S05-1HDCG     |
| 181M-02LFT      | 2305NZ-1HDCGI8  | 2308B-1DCG8     | 23S05-1HDCG8    |
| 181M-52LF       | 2305Nzt-1DCG    | 2308B-1DCGI     | 23S05-1HDCGI    |
| 181M-52LFT      | 2305Nzt-1DCG8   | 2308B-1DCGI8    | 23S05-1HDCGI8   |
| 181MI-02LF      | 2305Nzt-1DCGI   | 2308B-1HDCG     | 23S05E-1DCG     |
| 181MI-02LFT     | 2305Nzt-1DCGI8  | 2308B-1HDCG8    | 23S05E-1DCG8    |
| 2059GI-02LF     | 2308-1DCG       | 2308B-1HDCGI    | 23S05E-1DCGI    |
| 2059GI-02LFT    | 2308-1DCG8      | 2308B-1HDCGI8   | 23S05E-1DCGI8   |



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138

## PRODUCT/PROCESS CHANGE NOTICE (PCN)

### ATTACHMENT 2 - PCN #: A1208-01R1

#### Updated Affected Part Numbers

| IDT Part Number | IDT Part Number | IDT Part Number  | IDT Part Number |
|-----------------|-----------------|------------------|-----------------|
| 23S05E-1HDCG    | 441MI-13LF      | 49FCT3805ASOGI   | 49FCT805CTQG    |
| 23S05E-1HDCG8   | 441MI-13LFT     | 49FCT3805ASOGI8  | 49FCT805CTQG8   |
| 23S05E-1HDCGI   | 442M-22LF       | 49FCT3805BAQG    | 49FCT805CTSOG   |
| 23S05E-1HDCGI8  | 442M-22LFT      | 49FCT3805BAQG8   | 49FCT805CTSOG8  |
| 23S05T-1DCG     | 442MI-22LF      | 49FCT3805BAQGI   | 49FCT805SOG     |
| 23S05T-1DCG8    | 442MI-22LFT     | 49FCT3805BAQGI8  | 49FCT805SOG8    |
| 23S05T-1DCGI    | 443MI-58LF      | 49FCT3805BASOG   | 49FCT805SOGI    |
| 23S05T-1DCGI8   | 443MI-58LFT     | 49FCT3805BASOG8  | 49FCT805SOGI8   |
| 23S08-2HDCG     | 445R-24LF       | 49FCT3805BASOGI  | 501AMILF        |
| 23S08-2HDCG8    | 445R-24LFT      | 49FCT3805BASOGI8 | 501AMILFT       |
| 23S08-2HDCGI    | 445R-34LF       | 49FCT3805BQG     | 501AMLF         |
| 23S08-2HDCGI8   | 445R-34LFT      | 49FCT3805BQG8    | 501AMLFT        |
| 23S09-1DCG      | 445R-41LF       | 49FCT3805BQGI    | 501BMILF        |
| 23S09-1DCG8     | 445R-41LFT      | 49FCT3805BQGI8   | 501BMILFT       |
| 23S09-1DCGI     | 445R-57LF       | 49FCT3805BSOG    | 501MILF         |
| 23S09-1DCGI8    | 445R-57LFT      | 49FCT3805BSOG8   | 501MILFT        |
| 23S09-1HPGG     | 445R-58LF       | 49FCT3805BSOGI   | 501MLF          |
| 23S09-1HPGG8    | 445R-58LFT      | 49FCT3805BSOGI8  | 501MLFT         |
| 23S09-1HPGGI    | 445RI-34LF      | 49FCT3805DQGI    | 502MILF         |
| 23S09-1HPGGI8   | 445RI-34LFT     | 49FCT3805DQGI8   | 502MILFT        |
| 23S09E-1HDCGI   | 451M-07LF       | 49FCT3805EQGI    | 502MLF          |
| 23S09E-1HDCGI8  | 451M-07LFT      | 49FCT3805EQGI8   | 502MLFT         |
| 23S09T-1DCG     | 452M-15LF       | 49FCT3805PYG     | 511MILF         |
| 23S09T-1DCG8    | 452M-15LFT      | 49FCT3805PYG8    | 511MILFT        |
| 2402MLF         | 452M-18LF       | 49FCT3805PYGI    | 511MLF          |
| 2402MLFT        | 452M-18LFT      | 49FCT3805PYGI8   | 511MLFT         |
| 307M-02ILF      | 455R-31LF       | 49FCT3805QG      | 512MILF         |
| 307M-02ILFT     | 455R-31LFT      | 49FCT3805QG8     | 512MILFT        |
| 307M-02LF       | 475AG-19LF      | 49FCT3805QGI     | 512MLF          |
| 307M-02LFT      | 475AG-19LFT     | 49FCT3805QGI8    | 512MLFT         |
| 308RILF         | 49FCT3805-1PYG  | 49FCT3805SOG     | 514MLF          |
| 308RILFT        | 49FCT3805-1PYG8 | 49FCT3805SOG8    | 514MLFT         |
| 308RLF          | 49FCT3805APYG   | 49FCT3805SOGI    | 524MILF         |
| 308RLFT         | 49FCT3805APYG8  | 49FCT3805SOGI8   | 524MILFT        |
| 309RILF         | 49FCT3805APYGI  | 49FCT805ASOG     | 525R-02ILF      |
| 309RILFT        | 49FCT3805APYGI8 | 49FCT805ASOG8    | 525R-02ILFT     |
| 309RLF          | 49FCT3805AQG    | 49FCT805ASOGI    | 525R-02LF       |
| 309RLFT         | 49FCT3805AQG8   | 49FCT805ASOGI8   | 525R-02LFT      |
| 3732DG-28LF     | 49FCT3805AQGI   | 49FCT805BTQG     | 542MILF         |
| 3732DG-28LFT    | 49FCT3805AQGI8  | 49FCT805BTQG8    | 542MILFT        |
| 3732G-35LF      | 49FCT3805ASOG   | 49FCT805BTSOG    | 542MLF          |
| 3732G-35LFT     | 49FCT3805ASOG8  | 49FCT805BTSOG8   | 542MLFT         |



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138

## PRODUCT/PROCESS CHANGE NOTICE (PCN)

### ATTACHMENT 2 - PCN #: A1208-01R1

#### Updated Affected Part Numbers

| IDT Part Number | IDT Part Number | IDT Part Number | IDT Part Number |
|-----------------|-----------------|-----------------|-----------------|
| 548G-05ALF      | 570ALFT         | 5V41129PGGI     | 650R-01ILF      |
| 548G-05ALFT     | 570AT           | 5V41129PGGI8    | 650R-01ILFT     |
| 548GI-05ALF     | 570BILF         | 5V41186PGG      | 650R-01LF       |
| 548GI-05ALFT    | 570BILFT        | 5V41186PGG8     | 650R-01LFT      |
| 551AMILF        | 570BLF          | 5V41186PGGI     | 650R-07ILF      |
| 551AMILFT       | 570BLFT         | 5V41186PGGI8    | 650R-07ILFT     |
| 551AMLF         | 571MLF          | 5V41201PGG      | 650R-07LF       |
| 551AMLFT        | 571MLFT         | 5V41201PGG8     | 650R-07LFT      |
| 551MILF         | 574MILF         | 5V41201PGGI     | 650R-11ILF      |
| 551MILFT        | 574MILFT        | 5V41201PGGI8    | 650R-11ILFT     |
| 551MLF          | 574MLF          | 5V50013DCG      | 650R-21ILF      |
| 551MLF-TSW      | 574MLFT         | 5V50013DCG8     | 650R-21ILFT     |
| 551MLFT         | 580M-01ILF      | 5V9950PFG       | 650R-21LF       |
| 551MLFT-TSW     | 580M-01ILFT     | 5V9950PFG8      | 650R-21LFT      |
| 551MLN          | 580M-01LF       | 5V9950PFGI      | 650R-27ILF      |
| 551MLNT         | 580M-01LFT      | 5V9950PFGI8     | 650R-27ILFT     |
| 552AR-01LF      | 5P61006PGGI     | 601G-21LF       | 651AMILF        |
| 552AR-01LFT     | 5P61006PGGI8    | 601G-21LFT      | 651AMILFT       |
| 552ARI-01LF     | 5P90011PGGI     | 601GI-21LF      | 651MILF         |
| 552ARI-01LFT    | 5P90011PGGI8    | 601GI-21LFT     | 651MILFT        |
| 552R-01ILF      | 5T30553DCG      | 601M-01ILF      | 651MLF          |
| 552R-01ILFT     | 5T30553DCG8     | 601M-01ILFT     | 651MLFT         |
| 552R-01LN       | 5T30553DCGI     | 601M-01LF       | 662M-03LF       |
| 552R-01LNT      | 5T30553DCGI8    | 601M-01LFT      | 662M-03LFT      |
| 553MILF         | 5T9950APFGI     | 601M-02ILF      | 670M-01ILF      |
| 553MILFT        | 5T9950APFGI8    | 601M-02ILFT     | 670M-01ILFT     |
| 553MLF          | 5T9950PFGI      | 613MLF          | 670M-01LF       |
| 553MLFT         | 5T9950PFGI8     | 613MLFT         | 670M-01LFT      |
| 554G-01AILF     | 5V30014PGG      | 623AG-02LF      | 670M-02LF       |
| 554G-01AILFT    | 5V30014PGG8     | 623AG-02LFT     | 670M-02LFT      |
| 556M-04ILF      | 5V30014PGGI     | 623G-03LF       | 670M-03ILF      |
| 556M-04ILFT     | 5V30014PGGI8    | 623G-03LFT      | 670M-03ILFT     |
| 557M-01LF       | 5V41065PGG      | 623GI-03LF      | 670M-04ILF      |
| 557M-01LFT      | 5V41065PGG8     | 623GI-03LFT     | 670M-04ILFT     |
| 557MI-01LF      | 5V41065PGGI     | 627AG-04LF      | 670MI-01LFT     |
| 557MI-01LFT     | 5V41065PGGI8    | 627AG-04LFT     | 670MI-02LF      |
| 570A            | 5V41067PGG      | 650M-38LF       | 670MI-02LFT     |
| 570AI           | 5V41067PGG8     | 650M-38LFT      | 671AGI-28LF     |
| 570AILF         | 5V41067PGGI     | 650M-46LF       | 671AGI-28LFT    |
| 570AILFT        | 5V41067PGGI8    | 650M-46LFT      | 671AGI-38LF     |
| 570AIT          | 5V41129PGG      | 650MI-46LF      | 671AGI-38LFT    |
| 570ALF          | 5V41129PGG8     | 650MI-46LFT     | 672M-02ILF      |



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138

## PRODUCT/PROCESS CHANGE NOTICE (PCN)

### ATTACHMENT 2 - PCN #: A1208-01R1

#### Updated Affected Part Numbers

| IDT Part Number    | IDT Part Number | IDT Part Number  | IDT Part Number  |
|--------------------|-----------------|------------------|------------------|
| 672M-02ILFT        | 7150GLFT        | 74FCT3807DQGI8   | 813252CKI-02LFT  |
| 672M-02LF          | 7152AM-11LF     | 74FCT3807EPYG    | 82V2058XDAG      |
| 672M-02LFT         | 7152AM-11LFT    | 74FCT3807EPYG8   | 82V2084PFG       |
| 673M-01ILF         | 7152AMI-11LF    | 74FCT3807EPYGI   | 82V2084PFG8      |
| 673M-01ILFT        | 7152AMI-11LFT   | 74FCT3807EPYGI8  | 82V32021NLG      |
| 673M-01LF          | 7152M-01LF      | 74FCT3807EQGI    | 82V32021NLG8     |
| 673M-01LFT         | 7152M-01LFT     | 74FCT3807EQGI8   | 8440259DK-45LF   |
| 6P40097PGG         | 7152M-02LF      | 74FCT3807PYG     | 8440259DK-45LFT  |
| 6P40097PGG8        | 7152M-02LFT     | 74FCT3807PYG8    | 8440259DKI-45LF  |
| 6P40098PGG         | 7152MI-01LF     | 74FCT3807PYGI    | 8440259DKI-45LFT |
| 6P40098PGG8        | 7152MI-01LFT    | 74FCT3807PYGI8   | 844256DGILF      |
| 6T40150NLGI        | 7152MI-02LF     | 74FCT3807QG      | 844256DGILFT     |
| 6T40150NLGI8       | 7152MI-02LFT    | 74FCT3807QG8     | 844256DGLF       |
| 6T40169NLGI        | 74CB218CRLF     | 74FCT3807QGI     | 844256DGLFT      |
| 6T40169NLGI8       | 74CB218CRLFTR   | 74FCT3807QGI8    | 844S2416CKILF    |
| 6U40R001APGG       | 74FCT20807PYGI  | 74FCT3807SOG     | 844S2416CKILF/W  |
| 6U40R001APGG8      | 74FCT20807PYGI8 | 74FCT3807SOG8    | 844S2416CKILFT   |
| 6V10010SOGI        | 74FCT20807QGI   | 74FCT3807SOGI    | 8535AG-31LFHCLF  |
| 6V10010SOGI8       | 74FCT20807QGI8  | 74FCT3807SOGI8   | 8535AG-31LFT-HC  |
| 6V10024DCG         | 74FCT38072DCGI  | 74FCT3811APYGI   | 8535AGLF         |
| 6V10024DCG8        | 74FCT38072DCGI8 | 74FCT3811APYGI8  | 8535AGLFT        |
| 6V10033PGG         | 74FCT38074DCGI  | 74FCT3811PYGI    | 853S012AKILF     |
| 6V10033PGG8        | 74FCT38074DCGI8 | 74FCT3811PYGI8   | 853S012AKILFT    |
| 6V40088DNBGI       | 74FCT38075DCGI  | 74FCT807BTQG     | 8735AK-21LF      |
| 6V40088DNBGI8      | 74FCT38075DCGI8 | 74FCT807BTQG8    | 8735AK-21LFT     |
| 6V40111ANLGI       | 74FCT3807APYG   | 74FCT807BTQGI    | 9107-10CS08      |
| 6V40111ANLGI8      | 74FCT3807APYG8  | 74FCT807BTQGI8   | 9107-10CS08T     |
| 6V40132PGG         | 74FCT3807APYGI  | 74FCT807BTSOG    | 9112AM-16LF-TV0  |
| 6V40132PGG8        | 74FCT3807APYGI8 | 74FCT807BTSOG8   | 9112AM-16LFT-TV0 |
| 6V40154PGG         | 74FCT3807AQQ    | 74FCT807BTSOGI   | 9112AM-16LN      |
| 6V40154PGG8        | 74FCT3807AQQ8   | 74FCT807BTSOGI8  | 9112BF-17LF      |
| 6V49079APAGI       | 74FCT3807AQQI   | 74FCT807CTQG     | 9112BF-17LFT     |
| 6V49079APAGI8      | 74FCT3807AQQI8  | 74FCT807CTQG8    | 9112BF-17LN      |
| 6V49126NLGI        | 74FCT3807ASOG   | 74FCT807CTQGI    | 9112BF-17LN-INO  |
| 6V49126NLGI8       | 74FCT3807ASOG8  | 74FCT807CTQGI8   | 9112BF-17LNT     |
| 6V49R901-009ANLGI  | 74FCT3807ASOGI  | 74FCT807CTSOG    | 9112BF-17LNT-INO |
| 6V49R901-009ANLGI8 | 74FCT3807ASOGI8 | 74FCT807CTSOG8   | 9112BFI-17LF     |
| 6V60008DCG         | 74FCT3807DPYG   | 74FCT807CTSOGI   | 9112BFI-17LFT    |
| 6V60008DCG8        | 74FCT3807DPYG8  | 74FCT807CTSOGI8  | 9148BF-26        |
| 6V60028DCGI        | 74FCT3807DPYGI  | 810N252BKI-02LF  | 9148BF-26T-INO   |
| 6V60028DCGI8       | 74FCT3807DPYGI8 | 810N252BKI-02LFT | 9148CF-10T-IB0   |
| 7150GLF            | 74FCT3807DQGI   | 813252CKI-02LF   | 9148F-02T        |





Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138

## PRODUCT/PROCESS CHANGE NOTICE (PCN)

### ATTACHMENT 2 - PCN #: A1208-01R1

#### Updated Affected Part Numbers

| IDT Part Number   | IDT Part Number | IDT Part Number    | IDT Part Number   |
|-------------------|-----------------|--------------------|-------------------|
| 9148F-02T-IB0     | 9250BF-28T-IB0  | 9EMS9633BKILF-EMR  | 9FGL839AKLFT      |
| 9148F-02T-INO     | 9250BF-28T-INO  | 9EMS9633BKILFT     | 9FGV0631AKILF     |
| 9148F-12T-INO     | 9250BF-50T-INO  | 9EMS9633BKILFT-EMR | 9FGV0631AKILFT    |
| 9148F-18LF        | 9250BFI-27      | 9EMS9633BKLF       | 9FGV0631AKLF      |
| 9148F-18LFT       | 9250BFI-27T     | 9EMS9633BKLFT      | 9FGV0631AKLFT     |
| 9154A-04CS16T-A   | 9250CF-10T-IB0  | 9EPRS475BGLF       | 9LP525BF-2LF      |
| 9154A-27CS16T-IB0 | 9250CF-10T-INO  | 9EPRS475BGLFT      | 9LP525BF-2LFT     |
| 9154A-27CS16T-IB1 | 932SV883AKLF    | 9EPRS475CGLF       | 9LPRS142AGLF      |
| 9154A-27CS16T-IB2 | 932SV883AKLFT   | 9EPRS475CGLFT      | 9LPRS142AGLFT     |
| 9154A-27CS16T-INO | 932SV901AKLF    | 9EPRS488CKLF       | 9LPRS427CGLF      |
| 9154A-27CS16T-IN1 | 932SV901AKLFT   | 9EPRS488CKLFT      | 9LPRS427CGLFT     |
| 9155C-23CW20      | 93712EF         | 9EPRS525AGILF      | 9LPRS430BGLF      |
| 9155C-23CW20T     | 93712EFT        | 9EPRS525AGILFT     | 9LPRS430BGLFT     |
| 9170B-01CS08LF    | 93716AF         | 9EPRS525AGLF       | 9LPRS431AGLF      |
| 9170B-01CS08LFT   | 93716AFT        | 9EPRS525AGLFT      | 9LPRS431AGLFT     |
| 9170B-02CS08LF    | 93716AFT-IB0    | 9ERS3165BGILF      | 9LPRS432AGLF      |
| 9170B-02CS08LFT   | 93716BGLF       | 9ERS3165BGILFT     | 9LPRS432AGLFT     |
| 9173B-01CS08LF    | 93716BGLFT      | 9ERS3165BGLF       | 9LPRS436CKILF     |
| 9173B-01CS08LFT   | 93722CFLF       | 9ERS3165BGLFT      | 9LPRS436CKILFT    |
| 9173B-15CS08LF    | 93722CFLFT      | 9ERS3187BKILF      | 9LPRS436CKLF      |
| 9173B-15CS08LFT   | 93732AF         | 9ERS3187BKILFT     | 9LPRS436CKLFT     |
| 9179AM-12T        | 93732AFT        | 9ERS3187BKLF       | 9LPRS477DKLF      |
| 9179AM-12T-IB0    | 93789DF         | 9ERS3187BKLFT      | 9LPRS477DKLFT     |
| 9179BF-03         | 93789DFT        | 9FGL1212AKLF       | 9LPRS483BGLF      |
| 9179BF-03T        | 94228BF-QT0     | 9FGL1212AKLFT      | 9LPRS483BGLFT     |
| 9179BF-03T-CQ0    | 94228BFT-QT0    | 9FGL1214AKLF       | 9LPRS485DGLF      |
| 9179BF-03T-IB0    | 950811AGT-IB0   | 9FGL1214AKLFT      | 9LPRS485DGLFT     |
| 9179BF-03T-INO    | 954141CGLF      | 9FGL1216AGLF       | 9LPRS502SKLF      |
| 9212AF-13LF       | 954141CGLFT     | 9FGL1216AGLFT      | 9LPRS502SKLFT     |
| 9212AF-13LF-INO   | 954201BGLN      | 9FGL1218AKLF       | 9LPRS525AGILF     |
| 9212AF-13LFT      | 954201BGLNT     | 9FGL1218AKLFT      | 9LPRS525AGILFT    |
| 9212AF-13LFT-INO  | 960023CGLF      | 9FGL1220AKLF       | 9LPRS525AGLF      |
| 9212AF-13LN       | 960023CGLFT     | 9FGL1220AKLFT      | 9LPRS525AGLF-INT  |
| 9212AF-13LNT      | 9DBV0830AKILF   | 9FGL1222AKLF       | 9LPRS525AGLFT     |
| 9214DGLF          | 9DBV0830AKILFT  | 9FGL1222AKLFT      | 9LPRS525AGLFT-INT |
| 9214DGLFT         | 9DBV0830AKLF    | 9FGL639AKLF        | 9LPRS527AGLF      |
| 9250AF-51T-INO    | 9DBV0830AKLFT   | 9FGL639AKLFT       | 9LPRS527AGLFT     |
| 9250BF-12T-IB0    | 9EMS9633BFILF   | 9FGL699AKLF        | 9LRS3125BKILF     |
| 9250BF-12T-INO    | 9EMS9633BFILFT  | 9FGL699AKLFT       | 9LRS3125BKILFT    |
| 9250BF-16T-IB0    | 9EMS9633BFLF    | 9FGL839AKILF       | 9LRS3125BKLF      |
| 9250BF-16T-INO    | 9EMS9633BFLFT   | 9FGL839AKILFT      | 9LRS3125BKLFT     |
| 9250BF-27T-INO    | 9EMS9633BKILF   | 9FGL839AKLF        | 9LRS3165BGILF     |



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138

## PRODUCT/PROCESS CHANGE NOTICE (PCN)

### ATTACHMENT 2 - PCN #: A1208-01R1

#### Updated Affected Part Numbers

| IDT Part Number | IDT Part Number   | IDT Part Number   | IDT Part Number  |
|-----------------|-------------------|-------------------|------------------|
| 9LRS3165BGILFT  | 9LVRS720BKLFT     | 9VRS4420BKLFT-IN0 | MK1575-01GILFTR  |
| 9LRS3165BGLF    | 9P935AFLF         | 9VRS4808BGLF      | MK1575-01GLF     |
| 9LRS3165BGLFT   | 9P935AFLF-QN0     | 9VRS4808BGLFT     | MK1575-01GLFTR   |
| 9LRS3169BKILF   | 9P935AFLFT        | 9VRS4813BKLF      | MK1704ALF        |
| 9LRS3169BKILFT  | 9P935AFLFT-QN0    | 9VRS4813BKLFT     | MK1704ALFTR      |
| 9LRS3169BKLF    | 9P936AFLF         | 9VRS4818BKLF      | MK1707DLF        |
| 9LRS3169BKLFT   | 9P936AFLFT        | 9VRS4818BKLFT     | MK1707DLFTR      |
| 9LRS3177AKLF    | 9TCS1083ANLG      | 9VRS4883BKLF      | MK1707SILF       |
| 9LRS3177AKLFT   | 9TCS1083ANLG8     | 9VRS4883BKLFT     | MK1707SILFTR     |
| 9LRS3187AKILF   | 9UM701AKLF        | CV126PAG          | MK1707SLF        |
| 9LRS3187AKILFT  | 9UM701AKLFT       | CV126PAG8         | MK1707SLFTR      |
| 9LRS3187AKLF    | 9UM709BGILF       | CV128PAG          | MK1709SILF       |
| 9LRS3187AKLFT   | 9UM709BGILFT      | CV128PAG8         | MK1709SILFTR     |
| 9LRS3197AKLF    | 9UM709BGLF        | CV143PYG          | MK1709SLF        |
| 9LRS3197AKLFT   | 9UM709BGLFT       | CV143PYG8         | MK1709SLFTR      |
| 9LRS4103BKLF    | 9UMS9001AKLF      | CV152PVG          | MK1714-01RILF    |
| 9LRS4103BKLFT   | 9UMS9001AKLFT     | CV152PVG8         | MK1714-01RILFTR  |
| 9LRS4105BKLF    | 9UMS9633BFILF     | CV193DPAG         | MK1714-01RLF     |
| 9LRS4105BKLFT   | 9UMS9633BFILFT    | CV193DPAG8        | MK1714-01RLFTR   |
| 9LRS4157BKLF    | 9UMS9633BFLF      | LV810RILF         | MK1714-02RILF    |
| 9LRS4157BKLFT   | 9UMS9633BFLFT     | LV810RILFT        | MK1714-02RILFTR  |
| 9LRS4180AKLF    | 9UMS9633BFW3LF    | MK1491-06SLF      | MK1714-02RLF     |
| 9LRS4180AKLFT   | 9UMS9633BFW3LFT   | MK1491-06SLFTR    | MK1714-02RLFTR   |
| 9LRS4180BKLF    | 9UMS9633BKILF     | MK1491-09FILN     | MK1721-02SLF     |
| 9LRS4180BKLFT   | 9UMS9633BKILFT    | MK1491-09FILNTR   | MK1721-02SLFTR   |
| 9LRS4200AKLF    | 9UMS9633BKLF      | MK1491-09FLN      | MK1727-01DGILF   |
| 9LRS4200AKLFT   | 9UMS9633BKLFT     | MK1491-09FLNTR    | MK1727-01DGILFT  |
| 9LRS4206AKLF    | 9V41001AGLF       | MK1493-03BGILF    | MK1727-01DGILFTR |
| 9LRS4206AKLFT   | 9V41001AGLFT      | MK1493-03BGILFTR  | MK1727G-02LF     |
| 9LRS4210AKLF    | 9VRS4338DKLF      | MK1493-03BGLF     | MK1727G-02LFT    |
| 9LRS4210AKLFT   | 9VRS4338DKLF-INT  | MK1493-03BGLFTR   | MK1727GI-02LF    |
| 9LRS4850AKLF    | 9VRS4338DKLFT     | MK1493-05GILF     | MK1727GI-02LFT   |
| 9LRS4850AKLFT   | 9VRS4338DKLFT-INT | MK1493-05GILFTR   | MK1727GI-05LF    |
| 9LRS4903BKLF    | 9VRS4339BKLF      | MK1493-05GLF      | MK1727GI-05LFT   |
| 9LRS4903BKLFT   | 9VRS4339BKLFT     | MK1493-05GLFTR    | MK1728AM-01LF    |
| 9LVRS720AKILF   | 9VRS4420AKLF      | MK1493-05GLN      | MK1728AM-01LFT   |
| 9LVRS720AKILFT  | 9VRS4420AKLF-INT  | MK1493-05GLNTR    | MK2058-01SILF    |
| 9LVRS720AKLF    | 9VRS4420AKLFT     | MK1574-01SILF     | MK2058-01SILFTR  |
| 9LVRS720AKLFT   | 9VRS4420AKLFT-INT | MK1574-01SILFTR   | MK2059-01SILF    |
| 9LVRS720BKILF   | 9VRS4420BKLF      | MK1574-01SLF      | MK2059-01SILFTR  |
| 9LVRS720BKILFT  | 9VRS4420BKLF-IN0  | MK1574-01SLFTR    | MK2069-01GILF    |
| 9LVRS720BKLF    | 9VRS4420BKLFT     | MK1575-01GILF     | MK2069-01GILFTR  |



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138

## PRODUCT/PROCESS CHANGE NOTICE (PCN)

### ATTACHMENT 2 - PCN #: A1208-01R1

#### Updated Affected Part Numbers

| IDT Part Number | IDT Part Number | IDT Part Number | IDT Part Number  |
|-----------------|-----------------|-----------------|------------------|
| MK2069-04GILF   | MK2703BSILF     | MK2772-01SLF    | MK3807-01RILF    |
| MK2069-04GILFTR | MK2703BSILFTR   | MK2772-01SLFTR  | MK3807-01RILFTR  |
| MK2302S-01ILF   | MK2703BSLF      | MK3200SILF      | MK5811ASLF       |
| MK2302S-01ILFTR | MK2703BSLFTR    | MK3200SILFTR    | MK5811ASLFTR     |
| MK2302S-01LF    | MK2703SILF      | MK3200SLF       | MK5811ASLFTR-IB0 |
| MK2302S-01LFTR  | MK2703SILFTR    | MK3200SLFTR     | MK5811CMILF      |
| MK2304S-1ILF    | MK2703SLF       | MK3720DLF       | MK5811CMILFT     |
| MK2304S-1ILFT   | MK2703SLFTR     | MK3720DLFTR     | MK5811CMLF       |
| MK2304S-1LF     | MK2705SLF       | MK3721DLF       | MK5811CMLFT      |
| MK2304S-1LFT    | MK2705SLFTR     | MK3721DLFTR     | MK5812SLF        |
| MK2304S-2ILF    | MK2712SLF       | MK3722GLF       | MK5812SLFTR      |
| MK2304S-2ILFTR  | MK2712SLFTR     | MK3722GLFTR     | MK5814SLF        |
| MK2304S-2LF     | MK2716SLF       | MK3727CLF       | MK5814SLFTR      |
| MK2304S-2LFTR   | MK2716SLFTR     | MK3727CLFTR     | MK5818SLF        |
| MK2308S-2ILF    | MK2745-21SLF    | MK3727DLF       | MK5818SLFTR      |
| MK2308S-2ILFT   | MK2745-21SLFTR  | MK3727DLFTR     |                  |
| MK2308S-2LF     | MK2745-33GLF    | MK3727SLF       |                  |
| MK2308S-2LFTR   | MK2745-33GLFTR  | MK3727SLFTR     |                  |



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138

## PRODUCT/PROCESS CHANGE NOTICE (PCN)

### ATTACHMENT 3 - PCN #: A1208-01R1

#### Part Numbers Removed from PCN

| IDT Part Number  | IDT Part Number | IDT Part Number | IDT Part Number |
|------------------|-----------------|-----------------|-----------------|
| 2305A-1DCG8-PAC  | 91719BGLFT      | 954309BKLFT     | 9LRS954A4GLFT   |
| 552G-02ILN       | 9220AGLFT       | 954310BGLF      | 9P946AFLFT      |
| 552G-02ILNT      | 9248AF-128LF    | 954310BGLFT     | 9P952DFLF       |
| 553MILFT-PAC     | 9248AF-128LFT   | 954310CGLF      | 9P952DFLFT      |
| 557G-05ALF       | 9248AG-192LF    | 954310CGLFT     | 9P956AGLF       |
| 557G-05ALFT      | 9248AG-192LFT   | 954321AGLFT     | 9P956AGLFT      |
| 557GI-05ALF      | 9248BF-146LF    | 960001AFLF      | 9UMS9610BKLF    |
| 557GI-05ALFT     | 9248BF-146LFT   | 960001AFLFT     | 9UMS9610BKLFT   |
| 557GI-05ALFT-PAC | 9248BF-195LF    | 960006AFLF      | 9UMS9610CKLFT   |
| 651MILFT-PAC     | 9248BF-195LFT   | 960006AFLFT     | CV125PAG8       |
| 670M-03ILFT-PAC  | 9248CF-98LF     | 960009CFLF      | CV183-2APAG     |
| 83905AGILFT      | 9248CF-98LFT    | 960009CFLFT     | CV183-2APAG8    |
| 83905AGLFT       | 9250DF-30LFT    | 960013BFLF      | CV189BPAG8      |
| 9110-01CS14LFT   | 93705AFLFT      | 960013BFLFT     | CV193CPAG8      |
| 9112AG-16LF      | 93705CFLFT      | 9E4101AFILF     | CV194CPAG8      |
| 9112AG-16LFT     | 94211AFLF       | 9E4101AFILFT    |                 |
| 9112AM-16LF      | 94211AFLFT      | 9LPR311AKLFT    |                 |
| 9112AM-16LFT     | 950202CFLF      | 9LPR316AGLFT    |                 |
| 9112AM-16LNT     | 950202CFLFT     | 9LPR501PGLFT    |                 |
| 9112AM-17LF      | 950225CFLFT     | 9LPR501SGLF     |                 |
| 9112AM-17LFT     | 950401CGLF      | 9LPR501SGLFT    |                 |
| 9112AM-26LFT     | 950401CGLFT     | 9LPR502SGLFT    |                 |
| 9112AM-27LF      | 950508BFLFT     | 9LPR515CGLF     |                 |
| 9112AM-27LFT     | 950810CGLF      | 9LPR515CGLFT    |                 |
| 9112AM-76LFT     | 950810CGLFT     | 9LPR600CGLFT    |                 |
| 9112BM-17LF      | 950901BFLFT     | 9LPRS113AKLFT   |                 |
| 9112BM-17LFT     | 951464AGLF      | 9LPRS140CKLFT   |                 |
| 9112M-22LFT      | 951464AGLFT     | 9LPRS357AKLF    |                 |
| 91305AGILF       | 952603DFLFT     | 9LPRS357AKLFT   |                 |
| 91305AGILFT      | 952606PFLFT     | 9LPRS359AGLF    |                 |
| 91305AGLFT       | 952621CFLFT     | 9LPRS359AGLFT   |                 |
| 91305AMILF       | 952624AFLF      | 9LPRS477CKLFT   |                 |
| 91305AMILFT      | 952624AFLFT     | 9LPRS478CKLFT   |                 |
| 91305AMLF        | 952926CGLF      | 9LPRS501SGLF    |                 |
| 91305AMLFT       | 952926CGLFT     | 9LPRS501SGLFT   |                 |
| 91309AGILFT      | 953201BGLFT     | 9LPRS501SKLF    |                 |
| 91309AGLF        | 954101DGLF      | 9LPRS501SKLFT   |                 |
| 91309AGLFT       | 954101DGLFT     | 9LPRS502SGLF    |                 |
| 91309AMILFT      | 954105BFLFT     | 9LPRS502SGLFT   |                 |
| 91309AMLFT       | 954201BGLF      | 9LPRS511JGLF    |                 |
| 91718CMLF        | 954201BGLFT     | 9LPRS511JGLFT   |                 |
| 91718CMLFT       | 954309BKLF      | 9LPRS916JGLFT   |                 |



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138

## PRODUCT/PROCESS CHANGE NOTICE (PCN)

### ATTACHMENT 4 - PCN #: A1208-01R1

#### Part Numbers Added into PCN

| IDT Part Number  | IDT Part Number | IDT Part Number   | IDT Part Number   |
|------------------|-----------------|-------------------|-------------------|
| 1337GDCGK        | 570AILFT        | 813252CKI-02LF    | 9154A-27CS16T-IN1 |
| 180MI-01LF       | 570AIT          | 82V2058XDAG       | 9155C-23CW20      |
| 181MI-02LF       | 570ALF          | 82V2084PFG        | 9155C-23CW20T     |
| 2305B-1DCGI      | 570ALFT         | 82V32021NLG       | 9170B-01CS08LF    |
| 2305B-1HDCGI     | 570AT           | 82V32021NLG8      | 9170B-01CS08LFT   |
| 2305NZT-1DCGI    | 570BILF         | 8440259DK-45LF    | 9170B-02CS08LF    |
| 2308-1HDCGI      | 570BILFT        | 8440259DKI-45LF   | 9170B-02CS08LFT   |
| 2308-5HDCGI      | 570BLF          | 8440259DKI-45LFT  | 9173B-01CS08LF    |
| 2308B-1DCG       | 570BLFT         | 844256DGILF       | 9173B-01CS08LFT   |
| 2308B-1HDCGI     | 5T9950APFGI     | 844256DGLF        | 9179AM-12T        |
| 2309M-1          | 5T9950PFGI      | 844S2416CKILF     | 9179AM-12T-IB0    |
| 2309M-1HLF       | 5V30014PGG      | 844S2416CKILF/W   | 9179BF-03         |
| 2309M-1HLFT      | 5V41067PGG      | 844S2416CKILFT    | 9179BF-03T        |
| 2309M-1T         | 5V41067PGG8     | 8535AG-31LFHCLF   | 9179BF-03T-CQ0    |
| 2309MI-1         | 5V41067PGGI     | 8535AG-31LFT-HC   | 9179BF-03T-IB0    |
| 2309MI-1HLF      | 5V41067PGGI8    | 8535AGLF          | 9179BF-03T-INO    |
| 2309MI-1HLFT     | 5V41129PGGI     | 8535AGLFT         | 9212AF-13LF-INO   |
| 2309MI-1T        | 5V41186PGGI     | 853S012AKILF      | 9212AF-13LFT-INO  |
| 23S08-2HDCGI     | 5V41201PGG      | 8735AK-21LF       | 9212AF-13LN       |
| 23S09-1DCGI      | 5V9950PFG       | 9107-10CS08       | 9212AF-13LNT      |
| 23S09-1HPGG      | 5V9950PFG8      | 9107-10CS08T      | 9250AF-51T-INO    |
| 3732G-35LF       | 5V9950PFGI      | 9112AM-16LFT-TV0  | 9250BF-12T-IB0    |
| 442MI-22LF       | 601GI-21LF      | 9112AM-16LF-TV0   | 9250BF-12T-INO    |
| 442MI-22LFT      | 623GI-03LF      | 9112AM-16LN       | 9250BF-16T-IB0    |
| 445RI-34LF       | 623GI-03LFT     | 9112BF-17LN       | 9250BF-16T-INO    |
| 445RI-34LFT      | 650M-46LF       | 9112BF-17LN-INO   | 9250BF-27T-INO    |
| 49FCT3805-1PYG   | 650M-46LFT      | 9112BF-17LNT-INO  | 9250BF-28T-IB0    |
| 49FCT3805BAQG    | 650MI-46LF      | 9112BFI-17LF      | 9250BF-28T-INO    |
| 49FCT3805BAQGI   | 650R-07ILF      | 9148BF-26         | 9250BF-50T-INO    |
| 49FCT3805BASOG   | 670MI-01LFT     | 9148BF-26T-INO    | 9250BFI-27        |
| 49FCT3805BASOGI  | 670MI-02LF      | 9148CF-10T-IB0    | 9250BFI-27T       |
| 49FCT3805BASOGI8 | 6V60028DCGI     | 9148F-02T         | 9250CF-10T-IB0    |
| 548GI-05ALF      | 7152MI-02LF     | 9148F-02T-IB0     | 9250CF-10T-INO    |
| 551AMLF          | 7152MI-02LFT    | 9148F-02T-INO     | 932SV883AKLF      |
| 551AMLFT         | 74CB218CRLF     | 9148F-12T-INO     | 932SV901AKLF      |
| 551MLF-TSW       | 74FCT3807DPYG   | 9148F-18LF        | 93712EF           |
| 551MLFT-TSW      | 74FCT3807DPYG8  | 9148F-18LFT       | 93712EFT          |
| 551MLN           | 74FCT3807SOGI   | 9154A-04CS16T-A   | 93716AF           |
| 554G-01AILF      | 74FCT3811APYGI  | 9154A-27CS16T-IB0 | 93716AFT          |
| 570A             | 74FCT807BTQG    | 9154A-27CS16T-IB1 | 93716AFT-IB0      |
| 570AI            | 74FCT807BTQGI   | 9154A-27CS16T-IB2 | 93716BGLF         |
| 570AILF          | 810N252BKI-02LF | 9154A-27CS16T-INO | 93716BGLFT        |



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138

## PRODUCT/PROCESS CHANGE NOTICE (PCN)

### ATTACHMENT 4 - PCN #: A1208-01R1

#### Part Numbers Added into PCN

| IDT Part Number    | IDT Part Number | IDT Part Number   | IDT Part Number  |
|--------------------|-----------------|-------------------|------------------|
| 93732AF            | 9FGV0631AKLF    | 9P936AFLF         | MK1727G-02LFT    |
| 93732AFT           | 9LPRS142AGLF    | 9P936AFLFT        | MK2302S-01ILF    |
| 93789DF            | 9LPRS427CGLF    | 9TCS1083ANLG      | MK2304S-1LF      |
| 93789DFT           | 9LPRS430BGLF    | 9TCS1083ANLG8     | MK2308S-2ILF     |
| 94228BF-QT0        | 9LPRS430BGLFT   | 9UMS9633BFILF     | MK3200SILF       |
| 94228BFT-QT0       | 9LPRS432AGLF    | 9UMS9633BFILFT    | MK3727CLF        |
| 950811AGT-IB0      | 9LPRS436CKLF    | 9UMS9633BFLF      | MK3727SLF        |
| 954201BGLN         | 9LPRS485DGLF    | 9UMS9633BFLFT     | MK5811ASLFTR-IB0 |
| 954201BGLNT        | 9LPRS525AGILF   | 9UMS9633BFW3LF    |                  |
| 9DBV0830AKILF      | 9LPRS527AGLF    | 9UMS9633BFW3LFT   |                  |
| 9DBV0830AKILFT     | 9LRS3125BKILF   | 9UMS9633BKILF     |                  |
| 9DBV0830AKLF       | 9LRS3125BKILFT  | 9UMS9633BKILFT    |                  |
| 9DBV0830AKLFT      | 9LRS3125BKLF    | 9UMS9633BKLF      |                  |
| 9EMS9633BFILF      | 9LRS3125BKLFT   | 9UMS9633BKLFT     |                  |
| 9EMS9633BFILFT     | 9LRS3165BGILF   | 9V41001AGLF       |                  |
| 9EMS9633BFLF       | 9LRS3165BGILFT  | 9VRS4420AKLF      |                  |
| 9EMS9633BFLFT      | 9LRS3165BGLF    | 9VRS4420BKLF      |                  |
| 9EMS9633BKILF      | 9LRS3165BGLFT   | 9VRS4420BKLF-IN0  |                  |
| 9EMS9633BKILF-EMR  | 9LRS3169BKILF   | 9VRS4420BKLFT     |                  |
| 9EMS9633BKILFT     | 9LRS3169BKILFT  | 9VRS4420BKLFT-IN0 |                  |
| 9EMS9633BKILFT-EMR | 9LRS3169BKLF    | 9VRS4808BGLF      |                  |
| 9EMS9633BKLF       | 9LRS3169BKLFT   | 9VRS4813BKLF      |                  |
| 9EMS9633BKLFT      | 9LRS3177AKLF    | 9VRS4818BKLF      |                  |
| 9EPRS475BGLF       | 9LRS3177AKLFT   | 9VRS4883BKLF      |                  |
| 9EPRS475CGLF       | 9LRS3187AKILF   | CV126PAG          |                  |
| 9EPRS475CGLFT      | 9LRS3187AKILFT  | CV126PAG8         |                  |
| 9EPRS488CKLF       | 9LRS3187AKLF    | CV128PAG          |                  |
| 9EPRS488CKLFT      | 9LRS3187AKLFT   | CV128PAG8         |                  |
| 9ERS3165BGILF      | 9LRS3197AKLF    | CV143PYG          |                  |
| 9ERS3165BGILFT     | 9LRS3197AKLFT   | CV143PYG8         |                  |
| 9ERS3165BGLF       | 9LRS4180AKLF    | CV152PVG          |                  |
| 9ERS3165BGLFT      | 9LRS4180BKLF    | CV152PVG8         |                  |
| 9ERS3187BKILF      | 9LRS4200AKLF    | CV193DPAG         |                  |
| 9ERS3187BKLF       | 9LRS4210AKLF    | MK1493-03BGILF    |                  |
| 9FGL1212AKLF       | 9LRS4210AKLFT   | MK1493-05GLN      |                  |
| 9FGL1220AKLF       | 9LVRS720AKILF   | MK1493-05GLNTR    |                  |
| 9FGL639AKLF        | 9LVRS720BKILF   | MK1707DLF         |                  |
| 9FGL699AKLF        | 9LVRS720BKILFT  | MK1707SILF        |                  |
| 9FGL839AKILF       | 9P935AFLF       | MK1709SILF        |                  |
| 9FGL839AKLF        | 9P935AFLF-QN0   | MK1714-02RILF     |                  |
| 9FGV0631AKILF      | 9P935AFLFT      | MK1714-02RLF      |                  |
| 9FGV0631AKILFT     | 9P935AFLFT-QN0  | MK1727G-02LF      |                  |