



Integrated Device Technology, Inc.
 2975 Stender Way, Santa Clara, CA - 95054
 Phone #: (408) 727-6116 Fax #: (408) 727-2328

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: L-05-04 Last Buy Date: May 1, 2006
 Issue Date: May 2, 2005 Last Ship Date: July 31, 2006
 (3 months after last buy date)

PRODUCT(S) AFFECTED: ATTACHMENT Yes No
(List Replacement Part #(s), if any)

Selective Logic products will be discontinued. Please see attachment for the affected part# list.

Selective discontinued products may be available in different package types.
Please see attachment for additional details.

REASON FOR DISCONTINUANCE:

Replace slower speed with faster speed offerings Other: _____
 Obsolete Fab Technology / Process _____
 Obsolete Assembly Technology / Process _____
 Obsolete Package / Material _____
 Declined Market _____

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____ E-Mail Address: _____
 Name/Date: _____ Phone#: _____
 Title: _____ Fax# : _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGEMENT:

Received By: _____ Date: _____



2975 Stender Way, Santa Clara, CA - 95054
 Phone #: (408) 727-6116
 Fax #: (408) 727-2328

Attachment - PDN # L-05-04

Affected IDT Part No.	Replacement Part No.
IDT29FCT2052ATSO	No Replacement
IDT29FCT2052CTQ	No Replacement
IDT29FCT52ATQ	No Replacement
IDT29FCT52ATSO	No Replacement
IDT29FCT52CTQ	No Replacement
IDT29FCT52CTSO	No Replacement
IDT54FCT244ADB	No Replacement
IDT54FCT244ALB	No Replacement
IDT54FCT244DB	No Replacement
IDT54FCT244LB	No Replacement
IDT54FCT245ADB	No Replacement
IDT54FCT245ALB	No Replacement
IDT54FCT245DB	No Replacement
IDT54FCT245LB	No Replacement
IDT54FCT273ATDB	No Replacement
IDT54FCT273ATLB	No Replacement
IDT54FCT273CTDB	No Replacement
IDT54FCT273CTLB	No Replacement
IDT54FCT273TDB	No Replacement
IDT54FCT273TLB	No Replacement
IDT54FCT374ADB	No Replacement
IDT54FCT374ALB	No Replacement
IDT54FCT374DB	No Replacement
IDT54FCT374LB	No Replacement
IDT54FCT541ATDB	No Replacement
IDT54FCT541ATLB	No Replacement
IDT54FCT541CTDB	No Replacement
IDT54FCT541CTLB	No Replacement
IDT54FCT541TDB	No Replacement
IDT54FCT541TLB	No Replacement

Affected IDT Part No.	Replacement Part No.
IDT54FCT543ADB	No Replacement
IDT54FCT543ALB	No Replacement
IDT54FCT543DB	No Replacement
IDT54FCT543LB	No Replacement
IDT54FCT574ADB	No Replacement
IDT54FCT574ALB	No Replacement
IDT54FCT574DB	No Replacement
IDT54FCT574LB	No Replacement
IDT74ALVC162244PV	Available in PA Package
IDT74ALVCH16245PV	Available in PA/PF package
IDT74ALVCH16345PA	No Replacement
IDT74ALVCH16373PA	No Replacement
IDT74ALVCH16374PA	No Replacement
IDT74ALVCH16374PF	No Replacement
IDT74ALVCH16374PV	No Replacement
IDT74ALVCH16721PV	Available in PA Package
IDT74ALVCH16903PV	Available in PA Package
IDT74ALVCH16952PA	No Replacement
IDT74ALVCH16952PV	No Replacement
IDT74ALVCH32373BF	No Replacement
IDT74ALVCHR162269APA	No Replacement
IDT74ALVCHR16501PA	No Replacement
IDT74CBTLV16210PF	Available in PA Package
IDT74CBTLV16210PV	Available in PA Package
IDT74CBTLV16211PV	Available in PA/PF Package
IDT74CBTLV16212PF	Available in PA Package
IDT74CBTLV16212PV	Available in PA Package
IDT74CBTLV16214PA	No Replacement
IDT74CBTLV16214PF	No Replacement
IDT74CBTLV16214PV	No Replacement



2975 Stender Way, Santa Clara, CA - 95054

Phone #: (408) 727-6116

Fax #: (408) 727-2328

Attachment - PDN # L-05-04

Affected IDT Part No.	Replacement Part No.
IDT74CBTLV16245PV	Available in PA/PF Package
IDT74CBTLV16292PF	Available in PA Package
IDT74CBTLV16292PV	Available in PA Package
IDT74CBTLV16800PF	Available in PA/PV Package
IDT74CBTLV3244PY	Available in Q/PG package
IDT74CBTLV3245PY	Available in Q/PG package
IDT74CBTLV3251PY	Available in Q/PG package
IDT74CBTLV3253PG	IDT74CBTLV3253PGG
IDT74CBTLV3253PY	Available in Q/PGG Package
IDT74CBTLV3257PY	Available in Q/PG Package
IDT74CBTLV3383PG	No Replacement
IDT74CBTLV3383PY	No Replacement
IDT74CBTLV3383Q	No Replacement
IDT74CBTLV3384PY	Available in Q/PG Package
IDT74CBTLV3861PY	Available in Q/PG Package
IDT74CBTLV6800PY	Available in Q/PG Package
IDT74CBTLVR16292PA	No Replacement
IDT74CBTLVR16292PF	No Replacement
IDT74CBTLVR16292PV	No Replacement
IDT74CBTLVR3384PG	No Replacement
IDT74CBTLVR3384PY	No Replacement
IDT74CBTLVR3384Q	No Replacement
IDT74CBTLVR3861PG	No Replacement
IDT74CBTLVR3861PY	No Replacement
IDT74CBTLVR3861Q	No Replacement
IDT74CBTLVR3862PG	No Replacement
IDT74CBTLVR3862PY	No Replacement
IDT74CBTLVR3862Q	No Replacement
IDT74FCT138ATQ	No Replacement
IDT74FCT138ATSO	No Replacement

Affected IDT Part No.	Replacement Part No.
IDT74FCT138CTQ	No Replacement
IDT74FCT138CTSO	No Replacement
IDT74FCT139ATQ	No Replacement
IDT74FCT139ATSO	No Replacement
IDT74FCT139CTQ	No Replacement
IDT74FCT139CTSO	No Replacement
IDT74FCT151ATQ	No Replacement
IDT74FCT151ATSO	No Replacement
IDT74FCT151CTQ	No Replacement
IDT74FCT151CTSO	No Replacement
IDT74FCT162240ATPA	No Replacement
IDT74FCT162240ATPV	No Replacement
IDT74FCT162240ATPVG	No Replacement
IDT74FCT162240CTPA	No Replacement
IDT74FCT162240CTPV	No Replacement
IDT74FCT162240CTPVG	No Replacement
IDT74FCT162244ATPF	Available in PA/PV Package
IDT74FCT162244CTPF	Available in PA/PV Package
IDT74FCT162244ETPF	Available in PA/PV Package
IDT74FCT162245ATPF	Available in PA/PV Package
IDT74FCT162245CTPF	Available in PA/PV Package
IDT74FCT162260ATPV	No Replacement
IDT74FCT162260CTPV	No Replacement
IDT74FCT162260ETPV	No Replacement
IDT74FCT162374ATPF	Available in PA/PV Package
IDT74FCT162374CTPF	Available in PA/PV Package
IDT74FCT162374ETPF	Available in PA/PV Package
IDT74FCT162543ATPA	No Replacement
IDT74FCT162543ATPAG	No Replacement
IDT74FCT162543ATPV	No Replacement



2975 Stender Way, Santa Clara, CA - 95054
 Phone #: (408) 727-6116
 Fax #: (408) 727-2328

Attachment - PDN # L-05-04

Affected IDT Part No.	Replacement Part No.
IDT74FCT162543ATPVG	No Replacement
IDT74FCT162543CTPA	No Replacement
IDT74FCT162543CTPAG	No Replacement
IDT74FCT162543CTPV	No Replacement
IDT74FCT162543CTPVG	No Replacement
IDT74FCT16260ATPA	No Replacement
IDT74FCT16260ATPV	No Replacement
IDT74FCT16260CTPA	No Replacement
IDT74FCT16260CTPV	No Replacement
IDT74FCT16260ETPA	No Replacement
IDT74FCT16260ETPV	No Replacement
IDT74FCT162646ATPA	No Replacement
IDT74FCT162646ATPF	No Replacement
IDT74FCT162646ATPV	No Replacement
IDT74FCT162646CTPA	No Replacement
IDT74FCT162646CTPF	No Replacement
IDT74FCT162646CTPV	No Replacement
IDT74FCT162841ATPA	No Replacement
IDT74FCT162841ATPV	No Replacement
IDT74FCT162841CTPA	No Replacement
IDT74FCT162841CTPV	No Replacement
IDT74FCT163344APV	Available in PA Package
IDT74FCT163344CPV	Available in PA Package
IDT74FCT163501APA	No Replacement
IDT74FCT163501APF	No Replacement
IDT74FCT163501APV	No Replacement
IDT74FCT163501CPA	No Replacement
IDT74FCT163501CPF	No Replacement
IDT74FCT163501CPV	No Replacement
IDT74FCT163601APA	No Replacement

Affected IDT Part No.	Replacement Part No.
IDT74FCT163827APV	Available in PA Package
IDT74FCT163827CPV	Available in PA Package
IDT74FCT16501ATPV	Available in PA Package
IDT74FCT16501CTPV	Available in PA Package
IDT74FCT166244ATPA	Available in PV Package
IDT74FCT166244CTPA	Available in PV Package
IDT74FCT16652ATPA	No Replacement
IDT74FCT16652ATPV	No Replacement
IDT74FCT16652CTPA	No Replacement
IDT74FCT16652CTPV	No Replacement
IDT74FCT16823ATPA	No Replacement
IDT74FCT16823ATPV	No Replacement
IDT74FCT16823CTPA	No Replacement
IDT74FCT16823CTPV	No Replacement
IDT74FCT16823ETPA	No Replacement
IDT74FCT16823ETPV	No Replacement
IDT74FCT2240ATQ	No Replacement
IDT74FCT2240ATSO	No Replacement
IDT74FCT2240CTQ	No Replacement
IDT74FCT2240CTSO	No Replacement
IDT74FCT2244ATPG	Available in Q/SO Package
IDT74FCT2244CTPG	Available in Q/SO Package
IDT74FCT2245ATPG	Available in Q/SO Package
IDT74FCT2245CTPG	Available in Q/SO Package
IDT74FCT2257ATQ	No Replacement
IDT74FCT2257ATSO	No Replacement
IDT74FCT2257CTQ	No Replacement
IDT74FCT2257CTSO	No Replacement
IDT74FCT2373ATSO	Available in Q Package
IDT74FCT2373CTSO	Available in Q Package



2975 Stender Way, Santa Clara, CA - 95054
 Phone #: (408) 727-6116
 Fax #: (408) 727-2328

Attachment - PDN # L-05-04

Affected IDT Part No.	Replacement Part No.
IDT74FCT2374ATSO	Available in Q Package
IDT74FCT2374CTSO	Available in Q Package
IDT74FCT244ASO	No Replacement
IDT74FCT244ASOG	No Replacement
IDT74FCT244CSO	No Replacement
IDT74FCT244CSOG	No Replacement
IDT74FCT245ASO	No Replacement
IDT74FCT245CSO	No Replacement
IDT74FCT2541ATPG	No Replacement
IDT74FCT2541ATQ	No Replacement
IDT74FCT2541ATSO	No Replacement
IDT74FCT2541CTPG	No Replacement
IDT74FCT2541CTQ	No Replacement
IDT74FCT2541CTSO	No Replacement
IDT74FCT2543ATQ	No Replacement
IDT74FCT2543ATSO	No Replacement
IDT74FCT2543CTQ	No Replacement
IDT74FCT2543CTSO	No Replacement
IDT74FCT2574ATQ	No Replacement
IDT74FCT2574ATSO	No Replacement
IDT74FCT2574CTQ	No Replacement
IDT74FCT2574CTSO	No Replacement
IDT74FCT2646ATPG	No Replacement
IDT74FCT2646CTPG	No Replacement
IDT74FCT273ATPY	No Replacement
IDT74FCT273ATQ	No Replacement
IDT74FCT273ATSO	No Replacement
IDT74FCT273ATSOG	No Replacement
IDT74FCT273CTPY	No Replacement
IDT74FCT273CTQ	No Replacement

Affected IDT Part No.	Replacement Part No.
IDT74FCT273CTSO	No Replacement
IDT74FCT273CTSOG	No Replacement
IDT74FCT2827ATQ	No Replacement
IDT74FCT2827ATSO	No Replacement
IDT74FCT2827CTQ	No Replacement
IDT74FCT2827CTSO	No Replacement
IDT74FCT299ATQ	No Replacement
IDT74FCT299ATSO	No Replacement
IDT74FCT299CTQ	No Replacement
IDT74FCT299CTSO	No Replacement
IDT74FCT3245APY	Available in PG/Q Package
IDT74FCT3245ASO	Available in PG/Q Package
IDT74FCT3245PY	Available in PG/Q Package
IDT74FCT3245SO	Available in PG/Q Package
IDT74FCT373ATPG	Available in Q/SO/PY Pkg.
IDT74FCT373CTPG	Available in Q/SO/PY Pkg.
IDT74FCT374ATPG	Available in Q/SO/PY Pkg.
IDT74FCT374CTPG	Available in Q/SO/PY Pkg.
IDT74FCT3827AQ	No Replacement
IDT74FCT3827BQ	No Replacement
IDT74FCT541ASO	No Replacement
IDT74FCT541ATPG	No Replacement
IDT74FCT541ATPY	No Replacement
IDT74FCT541ATQ	No Replacement
IDT74FCT541ATSO	No Replacement
IDT74FCT541CSO	No Replacement
IDT74FCT541CTPG	No Replacement
IDT74FCT541CTPY	No Replacement
IDT74FCT541CTQ	No Replacement
IDT74FCT541CTSO	No Replacement



2975 Stender Way, Santa Clara, CA - 95054

Phone #: (408) 727-6116

Fax #: (408) 727-2328

Attachment - PDN # L-05-04

Affected IDT Part No.	Replacement Part No.
IDT74FCT543ASO	No Replacement
IDT74FCT543ATPY	Available in Q/SO Package
IDT74FCT543CSO	No Replacement
IDT74FCT543CTPY	Available in Q/SO Package
IDT74FCT543DTPY	Available in Q/SO Package
IDT74FCT573ASO	No Replacement
IDT74FCT573ATPG	Available in Q/SO Package
IDT74FCT573ATPY	Available in Q/SO Package
IDT74FCT573CSO	No Replacement
IDT74FCT573CTPG	Available in Q/SO Package
IDT74FCT573CTPY	Available in Q/SO Package
IDT74FCT574ATPG	Available in Q/SO Package
IDT74FCT574ATPY	Available in Q/SO Package
IDT74FCT574CTPG	Available in Q/SO Package
IDT74FCT574CTPY	Available in Q/SO Package
IDT74FCT621ATSO	IDT74FCT621ATSOG
IDT74FCT621TSO	IDT74FCT621TSOG
IDT74FCT646ATPY	No Replacement
IDT74FCT646ATQ	No Replacement
IDT74FCT646ATSO	No Replacement
IDT74FCT646CTPY	No Replacement
IDT74FCT646CTQ	No Replacement
IDT74FCT646CTSO	No Replacement
IDT74FCT652ATQ	No Replacement
IDT74FCT652ATSO	No Replacement
IDT74FCT652CTQ	No Replacement
IDT74FCT652CTSO	No Replacement
IDT74FCT821ATQ	No Replacement
IDT74FCT821ATSO	No Replacement
IDT74FCT821CTQ	No Replacement

Affected IDT Part No.	Replacement Part No.
IDT74FCT821CTSO	No Replacement
IDT74FCT827ATPG	No Replacement
IDT74FCT827ATQ	No Replacement
IDT74FCT827ATSO	No Replacement
IDT74FCT827CTPG	No Replacement
IDT74FCT827CTQ	No Replacement
IDT74FCT827CTSO	No Replacement
IDT74FST163211PA	No Replacement
IDT74FST163211PAG	No Replacement
IDT74FST163212PA	No Replacement
IDT74FST163232PA	No Replacement
IDT74FST163232PV	No Replacement
IDT74FST163233PA	No Replacement
IDT74FST163233PAG	No Replacement
IDT74FST163233PV	No Replacement
IDT74FST163244PV	Available in PA Package
IDT74FST163245PV	Available in PA Package
IDT74FST32XL384PV	Available in PA Package
IDT74LVC11APG	IDT74LVC11APGG
IDT74LVC125ADC	No Replacement
IDT74LVC125APG	No Replacement
IDT74LVC16373APF	PA/PV Package
IDT74LVC16374APF	IDT74LVC16374APFG
IDT74LVC16646APA	No Replacement
IDT74LVC16646APV	No Replacement
IDT74LVC16823APF	Available in PA/PV Package
IDT74LVC16827APV	Available in PA Package
IDT74LVC2244APG	No Replacement
IDT74LVC2245AQ	No Replacement
IDT74LVC273AQ	Available in PY/PG Package



2975 Stender Way, Santa Clara, CA - 95054
 Phone #: (408) 727-6116
 Fax #: (408) 727-2328

Attachment - PDN # L-05-04

Affected IDT Part No.	Replacement Part No.
IDT74LVC273ASO	Available in PY/PG Package
IDT74LVC374APG	No Replacement
IDT74LVC374APY	No Replacement
IDT74LVC374AQ	No Replacement
IDT74LVC374ASO	No Replacement
IDT74LVC377APG	No Replacement
IDT74LVC377APY	No Replacement
IDT74LVC377AQ	No Replacement
IDT74LVC377ASO	No Replacement
IDT74LVCH162244APV	Available in PA/PF Package
IDT74LVCH16245APF	Available in PA/PV Package
IDT74LVCH16276APA	No Replacement
IDT74LVCH16501APA	No Replacement
IDT74LVCH16501APV	No Replacement
IDT74LVCH16543APV	Available in PA Package
IDT74LVCH244APG	No Replacement
IDT74LVCH244APY	No Replacement
IDT74LVCH244AQ	No Replacement
IDT74LVCH245APG	No Replacement
IDT74LVCH245APY	No Replacement
IDT74LVCH245AQ	No Replacement
IDT74LVCH32244ABF	No Replacement
IDT74LVCHR162245APF	Available in PA Package
IDT74LVCHR162245APV	Available in PA Package
IDT74LVGR162245APF	Available in PA/PV Package
IDTQS316212PA	No Replacement
IDTQS316233PA	No Replacement
IDTQS316233PV	No Replacement
IDTQS316245PV	No Replacement
IDTQS3244PA	IDTQS3244PAG

Affected IDT Part No.	Replacement Part No.
IDTQS3245PA	Available in Q/SO Package
IDTQS32861Q	No Replacement
IDTQS32XL383Q1	No Replacement
IDTQS3384SO	Available in PA/Q Package
IDTQS3389Q	No Replacement
IDTQS3L383Q	No Replacement
IDTQS3VH16210PV	Available in PA Package
IDTQS3VH16211PV	Available in PA Package
IDTQS3VH16212PV	Available in PA Package
IDTQS3VH16233PV	Available in PA Package
IDTQS3VH16244PV	Available in PA Package
IDTQS3VH16245PV	Available in PA Package
IDTQS3VH16800PV	Available in PA Package
IDTQS3VH16861PV	Available in PA Package
IDTQS3VH16862PV	Available in PA Package
IDTQS3VH383Q	No Replacement
IDTQS3VH383SO	No Replacement
IDTQS3VH384PA	IDTQS3VH384PAG



2975 Stender Way, Santa Clara, CA - 95054

Phone #: (408) 727-6116

Fax #: (408) 727-2328

Attachment - PDN # L-05-04

Affected IDT Part No.	Replacement Part No.
5962-87628012A	No Replacement
5962-8762801RA	No Replacement
5962-87628022A	No Replacement
5962-8762802RA	No Replacement
5962-87629012A	No Replacement
5962-8762901RA	No Replacement
5962-87629022A	No Replacement
5962-8762902RA	No Replacement
5962-87630012A	No Replacement
5962-8763001RA	No Replacement
5962-87630022A	No Replacement
5962-8763002RA	No Replacement
5962-89513012A	No Replacement
5962-8951301RA	No Replacement
5962-89513022A	No Replacement
5962-8951302RA	No Replacement

Affected IDT Part No.	Replacement Part No.
5962-89730013A	No Replacement
5962-8973001LA	No Replacement
5962-89730023A	No Replacement
5962-8973002LA	No Replacement
5962-9221501M2A	No Replacement
5962-9221501MRA	No Replacement
5962-9221503M2A	No Replacement
5962-9221503MRA	No Replacement
5962-9221505M2A	No Replacement
5962-9221505MRA	No Replacement
5962-9223701M2A	No Replacement
5962-9223701MRA	No Replacement
5962-9223703M2A	No Replacement
5962-9223703MRA	No Replacement
5962-9223705M2A	No Replacement
5962-9223705MRA	No Replacement